



Localised area of paint
breakdown on box
girder soffit section, no
51 (west)



Areas of paint breakdown
throughout viaduct on cycle
track outer edge beam.



Areas of paint breakdown
located box sections 32,33
& 34x. outer beams 130 x
to 139x.



INSPECTION DEPARTMENT
South viaduct external inspection. (areas of paint breakdown.
DATE. 09/09/09