



INSPECTION DEPARTMENT
Billet Survey Main Span (East)
DATE. 2013.11.21

North East Main Span:

PP 48 - Remains in a satisfactory condition.

PP 50 - Remains in a satisfactory condition.

PP 52 - Remains in a satisfactory condition.

PP 54 - Remains in a satisfactory condition.

PP 56 - Remains in a satisfactory condition.

PP 58 - Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place – **Will monitor.**

PP 60 - Stringer No 1. packers missing, Stringer No 2 . wear-down of packer evident. **Will monitor.**

PP 62 - Stringers No 1,2 & 3 packers missing. **NOISY. Requires attention.**

PP 64 - Remains in a satisfactory condition.

PP 66 - Stringers No 1,2,3 & 4 wear-down on packers evident remains okay. **Will monitor.**

PP 68 - Stringer no. 2 packer missing, stringer nos. 1, 3 & 4 showing signs of wear – **NOISY. Requires attention.**

PP 70 - Stringers No 1,2 & 3. packer wear-down evident. **Will monitor.**

PP 72 - Stringer No1. packers missing. Stringers No 2,3 & 4 packer wear-down evident. **Will monitor.**

PP 74 - All stringers ok with packers in place, satisfactory - quiet

PP 76 - Stringer No3. packers missing, packers Stringers No1,2 & 4.wear-down evident . **Will monitor.**

PP 78 - All stringers ok with packers in place, satisfactory - quiet.

PP 80 - Stringer No 1 packers missing. Stringers No 2,3 & 4 packer wear-down evident. - **NOISY. Requires attention.**

PP 82 - Remains in a satisfactory condition.

PP 84 - All stringers ok with packers in place, satisfactory - quiet

PP 86 - All stringers ok with packers in place, satisfactory - quiet

PP 88 - Stringer nos. 1 & 2, 3 & 4 packers missing, stringer – **NOISY. Requires attention.**
2 Bolts missing on stringer No1. (east side)



INSPECTION DEPARTMENT
Billet Survey Main Span (East)
DATE. 2013.11.21

North East Main Span cont.....:

- PP 90 - Remains in a satisfactory condition.
- PP 92 - Remains in a satisfactory condition.
- PP 94 - Slight packer wear-down on Stringers No 1,2 &3. remains quiet.
- PP 96 - Stringer No2. packers missing, Stringers No 1,3 & 4 packer wear-down evident.
NOISY. Requires attention.
- PP 98 - All stringers ok with packers in place, satisfactory - quiet
- PP 100 - All stringers ok with packers in place, satisfactory - quiet

South East Main Span:

- PP 48 - Stringers No 1 & 2 packer wear- down. **Will monitor.**
- PP 50 - Stringer no 2. packers missing. Stringers 1,3 & 4 showing signs of packer wear-down, **NOISY. Requires attention.**
- PP 52 - Stringer Nos 2 & 3 packers missing, stringers No. 1 & 4 packer in place
NOISY. Requires attention.
- PP 54 - All stringers ok with packers in place, satisfactory - quiet
- PP 56 - Stringers Nos 1,2, 3 & 4. packer wear- down. Deck panel movement,
Requires attention.
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - All stringers ok with packers in place, satisfactory - quiet
- PP 62 - Stringer nos. 1, 2 & 3 packers missing , stringer no. 4 packer wear- down.
NOISY. Requires attention.
- PP 64 - Stringer no. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place –
Requires attention.
- PP 66 - Stringer no. 1 packers missing, Stringers No 2,3 & 4 packer wear-down evident.
Will monitor.

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet Survey November 2013\Billet Survey - East Main Span 2013.11. 21..doc



INSPECTION DEPARTMENT
Billet Survey Main Span (East)
DATE. 2013.11.21

PP 68 - All stringers ok with packers in place, satisfactory - quiet

South East Main Span cont.....:

PP 70 - All stringers ok with packers in place, satisfactory - quiet

PP 72 - Stringers No 1 & 2 packers missing. **Will monitor.**

PP 74 - Stringers No 1,2, 3, & 4. Excessive packer wear – down . **Requires attention.**

PP 76 - Stringer No 1, packers missing , Stringers No 2,3 & 4 packer wear – down evident.
Will monitor.

PP 78 - Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place –
Requires attention.

PP 80 - Stringers No. 1,2 & 3 packer wear-down evident , remains satisfactory.

PP 82 - Stringers No 1, 2, 3 & 4 ,packer wear-down evident , remains satisfactory.

PP 84 - Stringers No 1, 3 & 4 ,packer wear-down evident , remains satisfactory.

PP 86 - Stringer No.1 packers missing. remains satisfactory.

PP 88 - Stringer Nos 2,3 & 4 packers missing, Stringer No1 packer wear-down evident.
NOISY. Requires attention

PP 90 - Remains in a satisfactory condition.

PP 92 - Stringer No 1 & 4. packers missing . Stringers No. 2&3 showing signs of wear – down
NOISY. Requires attention.

PP 94 - Stringer nos. 1-4 showing signs of wear - quiet

PP 96 - All stringers ok with packers in place, satisfactory - quiet

PP 98 - Stringers no.1 & 2 packers missing, stringer nos. 3-4 packers showing signs of wear –
NOISY. Requires attention.

PP 100 – Stringer nos. 1-4 packers showing signs of wear - quiet