

Main Span: North East

- PP 48 Remains in a satisfactory condition.
- PP 50 Slight movement on deck panel, wear-down on packers No. 1 & 2. Will monitor.
- PP 52 Remains in a satisfactory condition.
- PP 54 Wear-down on packers No. 1 & 2. Packers missing on stringer No 3. Will monitor.
- PP 56 Remains in a satisfactory condition.

PP 58 - Stringer nos. 1, 2 & 3 packers missing, & 4 packers in place – NOISY. Requires attention.

PP 60 - Stringer No 1. packers missing, Stringer No 2. wear-down of packer evident. NOISY. Requires attention.

PP 62 - Remains in a satisfactory condition.

PP 64 - Remains in a satisfactory condition.

PP 66 - Stringers No 1,2,3 & 4 wear-down on packers evident .Billet No 2. Getting noisy.. Will monitor.

PP 68 - Remains in a satisfactory condition.

PP 70 - Stringers No 3 & 4. packer wear-down evident. Packers missing No 2. Packers loose No 1. Getting noisy , Will monitor.

PP 72 - Stringer No1 &2 packers missing. Stringers No,3 & 4 packer wear-down evident. NOISY. Requires attention.

PP 74 - Remains in a satisfactory condition.

PP 76 - Stringer No 3. packers missing, packers Stringers No1,2 & 4.wear-down evident . NOISY. Requires attention.

- PP 78 Remains in a satisfactory condition. .
- PP 80 Remains in a satisfactory condition.
- PP 82 Remains in a satisfactory condition.
- PP 84 Remains in a satisfactory condition.
- PP 86 Packer wear-down on stringers No 1,2,3 & 4. Will monitor.

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet Survey March 2014\Billet Survey - East Main Span 2014. 03 25..doc



- PP 88 Remains in a satisfactory condition.
- PP 90 Remains in a satisfactory condition.
- PP 92 Packers missing on stringers No 1,2 & 3. NOISY. Requires attention.
- PP 94 Remains in a satisfactory condition.
- PP 96 Remains in a satisfactory condition.

PP 98 - Packers missing on stringers No 1 & 2, packer wear – down on 3 & 4. NOISY. Requires attention.

PP 100 - Remains in a satisfactory condition.

Main Span: South East.

- PP 48 Stringers No 1 & 2 packer wear- down. Will monitor.
- PP 50 Remains in a satisfactory condition.
- PP 52 Remains in a satisfactory condition.
- PP 54 Remains in a satisfactory condition.
- PP 56 Remains in a satisfactory condition.
- PP 58 Packer wear-down on stringers 1,2,3 & 4. Will monitor.
- PP 60 Remains in a satisfactory condition.
- PP 62 Remains in a satisfactory condition.
- PP 64 Stringer no. 1 packers missing . Remains satisfactory.
- PP 66 Stringer no. 1 packers missing, Stringers No 2,3 & 4 packer wear-down evident. Will monitor.
- PP 68 Remains in a satisfactory condition.

PP 70 - Stringers No 1 Packer wear – down. Stringers No 2,3 & 4. Packers missing. NOISY. Requires attention.

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet Survey March 2014\Billet Survey - East Main Span 2014. 03 25..doc



- PP 72 Stringers No 1 & 2 packers missing. Will monitor.
- PP 74 Stringers No 1,2, 3, & 4. Excessive packer wear down . Requires attention.
- PP 76 Stringer No 1 & 2, packers missing , Stringers No 3 & 4 packer wear down evident. Will monitor.
- PP 78 Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place Requires attention.
- PP 80 Stringers No. 1 & 2 packers missing. packer wear-down stringers No 3 & 4. <u>Requires attention.</u>
- PP 82 Stringers No 1, 2, 3 & 4 , packer wear-down evident , remains satisfactory.
- PP 84 Stringers No 1,2, 3 & 4 ,packer wear-down evident , Will monitor.
- PP 86 Stringer No.1 packers wear-down . remains satisfactory.
- PP 88 Remains in a satisfactory condition.
- PP 90 Packers missing on stringers No 1 & 2. Packer wear-down evident on stringers No 3 &
 4. <u>Requires attention.</u>
- PP 92 Remains in a satisfactory condition.
- PP 94 Remains in a satisfactory condition.
- PP 96 Remains in a satisfactory condition.

PP 98 - Remains in a satisfactory condition.

PP 100 – Stringers No 1 & 2 packers missing . Packer wear- down on stringers No 3 & 4 Remains Quiet.