



Billet Survey Main Span (East)

DATE. 2015.07.15

Main Span: North East

- PP 48 Standard packers in place packer 1 missing, packers 2 & 3 wear down evident Noisy
- PP 50 Satisfactory, Hardox packers in place painted movement evident on packers 2 & 3
- PP 52 Satisfactory, standard packers in place
- PP 54 Satisfactory, Hardox packers in place
- PP 56 Satisfactory, standard packers in place
- PP 58 Satisfactory, Hardox packers in place on 1-3 painted, standard packer on 4
- PP 60 Satisfactory, Hardox packers in place on 1 & 2 painted, standard packers on 3 & 4
- PP 62 Satisfactory, Hardox packers in place painted
- PP 64 Satisfactory, Hardox packers in place on 1 & 2 painted, standard packers on 3 & 4
- PP 66 Satisfactory, Hardox packers in place painted
- PP 68 Satisfactory, Hardox packers in place painted
- PP 70 Satisfactory, Hardox packers in place painted
- PP 72 Satisfactory, Hardox packers in place painted
- PP 74 Satisfactory, standard packers in place
- PP 76 Satisfactory, Hardox packers in place painted
- PP 78 Standard packers in place wear down evident on packers 1, 2, 3 & 4 Noisy
- PP 80 Standard packers in place packer 1 missing, wear down evident on 2 & 3 (platform in place and marked up for repairs) **Noisy**
- PP 82 Satisfactory, standard packers in place
- PP 84 Satisfactory, standard packers in place
- PP 86 Satisfactory, Hardox packers in place painted
- PP 88 Satisfactory, standard packers in place
- PP 90 Standard packers in place packer 1 missing, wear down evident on packer 2 Noisy

G:\Dd\T&P\Rnmmd\Branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\PDF Version Amey - Forth Bridges Unit Operating Contract - From 01.06.15\Main Span\Deck Half Joint Survey\Billet Survey July 2015\Billet Survey - East Main Span.Doc





Billet Survey Main Span (East)

DATE. 2015.07.15

- PP 92 Satisfactory, Hardox packers in place
- PP 94 Satisfactory, Hardox packers in place
- PP 96 Satisfactory, standard packers in place wear down evident on packer 1
- PP 98 Satisfactory, Hardox packers in place painted
- PP 100 Satisfactory, Hardox packers in place painted

Main Span: South East.

- PP 48 Satisfactory, Hardox packers in place painted slight movement evident on packer 2
- PP 50 Satisfactory, standard packers in place
- PP 52 Satisfactory, standard packers in place packer 2 missing Monitor
- PP 54 Standard packers in place packer 1 wear down evident, packer 2 missing, packers 3 & 4 ok Noisy
- PP 56 Satisfactory, standard packers in place slight wear down evident on packers 3 & 4
- PP 58 Satisfactory, Hardox packers in place painted
- PP 60 Satisfactory, standard packers in place slight wear down on 1 & 4, bolt sheared on Packer 4 East face
- PP 62 Satisfactory, standard packers in place
- PP 64 Standard packers in place packer 1 missing, wear down evident on packers 2, 3 & 4 Noisy
- PP 66 Satisfactory, Hardox packers in place painted
- PP 68 Satisfactory, standard packers in place slight wear down on packers 1 & 2
- PP 70 Satisfactory, Hardox packers in place painted
- PP 72 Satisfactory, Hardox packers in place on 1 & 2 painted, standard packers on 3 & 4
- PP 74 Satisfactory, Hardox packers in place painted

G:\Dd\T&P\Rnmmd\Branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\PDF Version Amey - Forth Bridges Unit Operating Contract - From 01.06.15\Main Span\Deck Half Joint Survey\Billet Survey July 2015\Billet Survey - East Main Span.Doc





Billet Survey Main Span (East)

DATE. 2015.07.15

- PP 76 Satisfactory, Hardox packers in place painted
- PP 78 Satisfactory, Hardox packers in place on 1,2 & 4 painted, standard packer on 3
- PP 80 Satisfactory, Hardox packers in place painted
- PP 82 Standard packers in place wear down evident Monitor
- PP 84 Standard packers in place wear down evident on packers Noisy
- PP 86 Satisfactory, standard packers in place wear down evident on 1 & 2, loose bolt on billet 1 (West face) **Noisy**
- PP 88 Satisfactory, standard packers in place
- PP 90 Satisfactory, Hardox packers in place painted
- PP 92 Standard packers in place 1, 2 & 3 wear down evident Noisy
- PP 94 Satisfactory, standard packers in place
- PP 96 Standard packers in place packer 1 missing, wear down evident on packers 2 & 3, packer 4 ok Noisy
- PP 98 Satisfactory, standard packers in place
- PP 100 Satisfactory, Hardox packers in place painted Billet no. 1 replaced





Billet Survey Main Span (East)

DATE. 2015.07.15