

On the Southbound Carriageway

Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. Plate noisier on this inspection will require attention soon.

Southbound Carriageway SE1 – Very noisy this inspection requires to be repaired A.S.A.P. (Repair works carried out Wednesday N/ shift 25/11/2015.) Movement & Noise still evident on plate No 1. Further works require to plate No 1. Information. : combe plates repaired on dayshift under bridge closure. 2015.12.16. (I.Alexander & G.Hall) Northbound Carriageway – All plates satisfactory.

Inspectors. :

Date.:

H:\Viaduct Expansion Joint weekly Inspections 2015\Combe plate weekly survey sheet 2015.12.16..doc



INSPECTION DEPARTMENT Combe plate weekly survey sheet DATE. 2015.12.15.