



**INSPECTION DEPARTMENT** 

CYCLETRACK, BALUSTRADE, AIR, WATER INSPECTION EAST SIDE Engineer Defects

DATE: 02/12/09



### <u>P.P. 70 N.E.</u> 2" TAKE OFF NIPPLE ON AIR RING

MAIN HEAVILY CORRODED TO POINT OF HOLING



## P.P. 100 N.E.

I<sup>ST</sup> POST NORTH OF P.P. HAS CRACK TO BALUSTRADE POST BASE WELD



# P.P. 94-95 S.E.

DB35 NAV BOX TOP SUPPORT LOOSE





#### **INSPECTION DEPARTMENT**

CYCLETRACK, BALUSTRADE, AIR, WATER INSPECTION EAST SIDE Engineer Defects

DATE: 02/12/09



## P.P. 78-79 S.E.

PLASTIC ELECTRICAL BOX TIE WRAPPED CLOSED, FIXINGS REQUIRE REPAIR.



## P.P. 49-50 N.E.

AIR TAKE OFF POINT, BEGINNING TO SHOW SIGNS OF WALL THINNING. REPLACE NIPPLES.