

The main tower cycle track expansion joints were inspected on the above date, general findings as follows:

Extensive wear down on sliding strips & apron plates remains as last inspection albeit deterioration continues.

Tensioning Assemblies: Sample inspections of the liquid spring assemblies have been carried out both this inspection and last, both show complete breakdown of the liquid pistons.

Photos can be found on System "G", "P" drive, BC09, also a sample photo is attached to this report showing the collapsed piston at the south west tower location.

Details entered on the maintenance programme computer system.

Inspectors: