

General Inspection Report

(BC06)

REPORT No.155

DATE: 15/10/2003 TO 17/10/2003

EXPANSION JOINTS CYCLETRACK N & S

THE CYCLE TRACK EXPANSION JOINTS AT BOTH THE NORTH & SOUTH MAIN TOWERS (BOTH MAIN SPAN & SIDE SPANS) WERE VISUALLY INSPECTED OVER THE ABOVE DATES, GENERAL FINDINGS WERE AS FOLLOWS. :

TOPSIDE. : STATUS WITH REGARDS TO WEARDOWN ON THE SLIDING PLATES & APRON PLATES REMAIN AS LAST REPORT. THE ABOVE WEAR CONTINUES TO HAVE AN EFFECT ON THE BITUMOUS SURFACE BELOW. INSPECTION OF TENSIONING ARRANGEMENT NOT POSSIBLE AS PLATE SCREWS ON THE TOP FACE OF THE APRON PLATES SEIZED.

UNDERSIDE. : ALL PLATEWORK AND FIXINGS REMAIN IN A SATISFACTORY CONDITION.

ALL DEFECTS DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTOR. :