

General Inspection Report

(BC15)

REPORT No.109

VIADUCT INTERNAL

DATE: 26/02/2002 TO 07/03/2002

THE NORTH AND SOUTH VIADUCT BOX GIRDER INTERNALS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE ABOVE DATES, THE GENERAL FINDINGS ARE AS FOLLOWS:

STRUCTURALLY: THE BOX GIRDERS WERE FOUND TO BE IN A SATISFACTORY CONDITION, ONLY 3 off LOCATIONS OF MINOR CORROSION/PAINT BREAKDOWN BEING REPORTED.

FANS: FIVE OF THE SIX FANS CHECKED OUT OPERATION, THE S.W.ABUTMENT FAN DID **NOT** WORK WHEN SWITCHED TO TEST.

LIGHTING: CONSIDERABLE NUMBERS OF LIGHTS WERE NOT WORKING AT TIME OF INSPECTION, ie: S.E.=44, S.W.=37, N.E.=1 & N.W.=1, TOTAL=83 off.

ALL DEFECTS DETAILED AND ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS: