General Inspection Report

DATE: 18/03/2002 TO 03/04/2002

(BC11) REPORT No.112 SIDE SPAN NORTH

THE NORTH SIDE SPAN WAS INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE ABOVE DATES, AND GENERAL FINDINGS WERE AS FOLLOWS:

STRUCTURALLY: ON THE WHOLE THE SIDE SPAN WAS FOUND TO BE IN A SATISFACTORY CONDITION. REMEDIAL WORKS ON MISSING BOLTS HAS BEEN CARRIED OUT SINCE LAST INSPECTION, AND ALTHOUGH SEVEN BOLTS WERE REPLACED, A FURTHER FOUR WERE LOCATED DURING THIS INSPECTION.

END TRIMMERS: WELD CRACKS WERE LOCATED ABOVE "C" LINE WALKWAYS AT THREE LOCATIONS ON THE SOUTHBOUND CARRIAGEWAY (SLOW LANE) AT PPs, 6,18 & 28.

<u>PAINTWORK & CORROSION</u>: AREAS OF PAINT BREAKDOWN & CORROSION REMAIN AS PREVIOUS REPORTS, NO PAINTING HAS BEEN CARRIED OUT SINCE LAST INSPECTION.

<u>WALKWAYS</u>: ALL WALKWAYS WERE FOUND TO BE SATISFACTORY, ALTHOUGH STILL CLIPS & FIXINGS LOOSE IN SOME AREAS.

ALL DEFECTS RECORDED AND ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS: