

General Inspection Report

(BC15)

REPORT No.142

VIADUCT INTERNAL N& S

DATE: 01/04/2003 TO 04/04/2003

THE NORTH AND SOUTH VIADUCT BOX GIRDER INTERNALS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE ABOVE DATES, THE GENERAL FINDINGS ARE AS FOLLOWS:

STRUCTURALLY: THE BOX GIRDERS WERE FOUND TO BE IN A SATISFACTORY CONDITION, MINOR CORROSION AREAS RECORDED ON STRUCTURE PROGRAMME.

FANS: FIVE OF THE SIX FANS CHECKED WERE FOUND TO BE SATISFACTORY. THE S.W. ABUTMENT FAN DID **NOT** OPERATE WHEN SWITCHED TO TEST.

LIGHTING: LIGHTS **NOT** WORKING AS FOLLOWS:

S.E.=15, S.W.=11. N.E.=9. N.W.=9. **Total = 44.**

HOUSEKEEPING: ELECTRICAL / ELECTRONIC DEBRIS FOUND THROUGHOUT.

BIRD DROPPINGS AND NESTING DEBRIS FOUND IN THE NORTH SECTIONS OF BOTH SOUTH EAST & WEST BOX GIRDERS (S3).

INSPECTORS: