

General Inspection Report

(BC11)

REPORT No.143

SIDE SPAN NORTH

DATE: 08/04/2003 TO 29/04/2003

THE NORTH SIDE SPAN WAS INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE ABOVE DATES,GENERAL FINDINGS WERE AS FOLLOWS:

STRUCTURALLY: ON THE WHOLE,THE STEELWORK APPEARS IN A SATISFACTORY CONDITION.THERE WAS **5 off** BROKEN BOLTS LOCATED DURING THIS INSPECTION, **1 off** ADDITION TO THE LAST INSPECTION.

PAINTWORK / CORROSION: REMAINS AS PREVIOUS REPORTS REGARDING TRUSSES ECT,NO PAINTING CARRIED OUT THIS PERIOD.

END TRIMMERS: BROKEN WELDS REPORTED AT LOCATIONS PP 18 & 26,DURING THIS INSPECTION.

WALKWAYS: ALL APPEAR INTACT,THE FLOOR CLIP CORROSION REMAINS AS LAST INSPECTION.

SERVICE DUCTS: CLAMPS AND FIXINGS NOW AT A MAJOR CORROSION LEVEL IN SOME AREAS.

ALL DEFECTS RECORDED AND ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS.