

# General Inspection Report

(BC13)

REPORT No.185

SIDE TOWERS N & S

DATE: 21/03/2005 TO 24/03/2005

Both the North & South side towers were visually inspected between the above dates, general findings were as follows. :

**Generally.** : The Side Tower structures appear in a satisfactory condition, with only **8 in** **No** element defects recorded.

**Post Tensioned Cables.** : It has now been confirmed by the **E.S.M.** that the **south** cables are to be removed, **Method Statement etc** with **E.S.M.** for work programming. **North** cables in a satisfactory condition.

**Rocker Saddle Bay.** : Access ladders & handrails were removed & replaced by **Spencers**, joining welds **primed only**, require to be repainted. ( **N/W** still **incomplete** at time of inspection. )

**Access.** : The **N/W Base** door was not accessible with keys supplied by operations. ( from either **inside or outside.** )

All defects are detailed & entered on the structure report programme.

**Inspectors. :**