

General Inspection Report

(BC15)

REPORT No 192.

DATE: 18/05/05 TO 20/05/05.

VIADUCT INTERNAL.

The North & South viaduct box girder internals were visually inspected over the above dates, the general findings were as follows. :

STRUCTURALLY. : On inspection the box girders were found to be in a satisfactory condition. Areas of minor corrosion recorded on the structure report programme.

FANS. : All units operational at time of inspection when tested, with the exception of the **S/W** abutment unit which was **non – functional** on test. (Possibly tripped)

LIGHTING. : Total number of lights **non – functional recorded at time of inspection. = 11.** Breakdown as follows : **S/W = 1. S/E = 3. & N/E = 7.**

HOUSEKEEPING. : Box girder **N/W No 1, at access hatch.** various items stored in this location. **ie,** scaffold, rope, wood etc. **N/E No20x,** empty boxes & other debris require to be removed.

All defects recorded & entered on the structure report programme.

Inspectors :