# **General Inspection Report**

DATE: 10/05/1999 TO 12/05/1999

(BC08/14) REPORT No.44 CHORD INTERNALS

AN INTERNAL INSPECTION OF THE CHORD INTERNALS AT SIX AVAILABLE LOCATIONS WAS CARRIED OUT AT THE REQUEST OF THE D.G.M. THE FINDINGS ARE AS FOLLOWS:

### TOP CHORD.

#### **PP80 S.E.:**

PAINT COLOUR: BLUE.

<u>CONDITION:</u> MEDIUM CORROSION/PAINT BREAKDOWN ON TOP & BOTTOM FACES, SLIGHT CORROSION ON SIDE WALLS, DIAMOND SPLICE PLATES CLEAN.

# **PP82 S.E.:**

PAINT COLOUR: BLUE.

<u>CONDITION:</u> MEDIUM CORROSION/PAINT BREAKDOWN ON TOP & BOTTOM FACES, SLIGHT CORROSION ON SIDE WALLS, DIAMOND SPLICE PLATES CLEAN.

#### **PP80 S.W.:**

PAINT COLOUR: BLUE.

<u>CONDITION</u>: VERY CLEAN, VERY MINOR RUST WATER STAINING AT BASE OF SUSPENDER SCREWED ROD HOUSING TUBE.

## **PP82 S.W.:**

PAINT COLOUR: BLUE.

<u>CONDITION:</u> MEDIUM CORROSION/PAINT BREAKDOWN ON TOP & BOTTOM FACES, SLIGHT CORROSION ON SIDE WALLS, DIAMOND SPLICE PLATES CLEAN.

#### **BOTTOM CHORD.**

## **PP39 SE & SW:**

PAINT COLOUR: YELLOW.

<u>CONDITION</u>: MEDIUM CORROSION/PAINT BREAKDOWN ON TOP & BOTTOM FACES, SLIGHT CORROSION ON SIDE WALLS, DIAMOND SPLICE PLATES CLEAN.

#### **INSPECTOR:**

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\General\General Report No 44. Chord Internals 10.05.99.doc