

# General Inspection Report

(BC06)

REPORT No.49

DATE: 18/06/1999 TO 24/06/1999

EXPANSION JOINTS

BOTH THE NORTH AND SOUTH VIADUCT EXPANSION JOINTS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE DATES ABOVE, THE GENERAL FINDINGS ARE AS FOLLOWS:

**STRUCTURALLY:** THE STEELWORK WAS FOUND TO BE IN A SATISFACTORY CONDITION, ALBEIT WITH SOME MINOR CORROSION EVIDENT TO UNDERSIDES.

**FIXINGS:** SOUTH JOINT FIXINGS ARE INTACT, NORTH JOINT FIXINGS ARE AS LAST INSPECTION ie, 4 off COMB PLATE NUTS MISSING.

**DRAINAGE:** TROUGH SHOWING SIGNS OF MINOR CORROSION/PAINT BREAKDOWN.

ALL DEFECTS DETAILED AND ENTERED ON STRUCTURE REPORT PROGRAMME.

**INSPECTORS:**

K.PERRYMAN.

G.HAMILTON