

# General Inspection Report

(BC11)

REPORT No.52

DATE: 09/09/1999 TO 01/10/1999

SIDE SPAN NORTH

SIDESPANS WHERE VISUALLY INSPECTED OVER THE ABOVE DATES , THE ACTUAL INTERMITTANT PERIOD OF INSPECTION WAS APPROX THREE WEEKS.

**STRUCTURAL STEELWORK:** GENERALLY FOUND TO BE IN A SATISFACTORY CONDITION WITH ONLY 4 OFF BOLTS MISSING, VARIOUS ( AS EXPECTED ) AREAS OF MINOR CORROSION/PAINTWORK BREAKDOWN ACROSS THE SPAN

**WALKWAYS :** GENERALLY SATISFACTORY ALLTHOUGH STILL HAVE LOOSE CLIPS & SLIGHT CORROSION THROUGHOUT .

THE SIDESPAN ON THE WHOLE WAS FOUND TO BE IN SATISFACTORY CONDITION WITH ALL DEFECTS ( 39No ) DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME .

**NOTE.** FURTHER INSPECTIONS OF THE TOP CHORD & INNER BALUSTRADE AREAS WILL BE REQUIRED IN DUE COURSE BECAUSE OF SUSPENDER REPLACEMENT WORKS ie SCAFFOLDING & HEAVY COMPONENT INSTALLATION WORKS ONGOING .

**INSPECTORS :**