

# General Inspection Report

(BC06)  
REPORT No.74  
EXPANSION JOINT

DATE: 20/09/2000 TO 21/09/2000

BOTH THE NORTH AND SOUTH **VIADUCT** EXPANSION JOINTS WERE VISUALLY INSPECTED OVER THE ABOVE DATES, GENERAL FINDINGS AS FOLLOWS:

**STRUCTURALLY:** THE STEELWORK WAS FOUND TO BE IN A SATISFACTORY CONDITION, WITH SOME CORROSION EVIDENT TO UNDERSIDES.

**FIXINGS:** GENERALLY **ALL** THE FIXINGS SHOW SIGNS OF HEAVY CORROSION, THE SITUATION AT THE NORTH JOINT REMAINS THE SAME WITH REGARD TO THE MISSING NUTS ETC.

**NOTE:** **NORTH JOINT**, BANGING CLEARLY APPARENT AT NORTHBOUND SLOW LANE, E.S.M. INFORMED AND ATTENDED.

DETAILS ENTERED ON STRUCTURE REPORT PRPGRAMME.

**INSPECTORS:**