General Inspection Report

(BC13) REPORT No.83 SIDE TOWERS N & S

DATE: 28/02/2001 TO 07/03/2001

BOTH NORTH & SOUTH TOWERS WERE VISUALLY INSPECTED OVER AN

INTERMITTANT PERIOD BETWEEN THE ABOVE DATES. GENERAL FINDINGS

WERE AS FOLLOWS.:

GENERALLY:

THE STRUCTURAL CONDITION APPEARS SATISFACTORY.

POST-TENSIONED CABLES.:

IN THE S/E LEG, E/ WALL, CABLE No 4 IS NOW

AS CABLE No 5 ON THE W $\!/$ WALL COMPLETELY SEVERED. IN THE S/W LEG

ON THE E/WALL, CABLE No 10 HAS 1 STRAND BROKEN. HEAVY CORROSION

IS EVIDENT ON ALL CABLES.

IT SHOULD BE NOTED THAT ALL LEG BASES WERE DRY AT TIME OF INSPECTION.

CYCLE TRACK SOFFITS.:

THE CABLE / CONDUIT BRACKETS AT THE CYCLE-TRACK SOFFITS, ARE NOW SHOWING SIGNS OF MEDIUM CORROSION. ELECTRICAL CABLE SLEEVE PROTECTION ON CABLES LOCATED ON ALL

FOUR SADDLE WELL FLOORS ARE DETERIORATING RAPIDLY/ NON EXISTANT

IN SOME AREAS.

ALL DEFECTS ARE DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS: