



INSPECTION DEPARTMENT

SOUTH VIADUCT EXTERNAL. (EAST) LIGHTING COLUMNS.

DATE. 18/09/09



DETERIORATION OF PROTECTIVE MEMBRANE ON LIGHTING COLUMN BASES



DETERIORATION OF PROTECTIVE MEMBRANE ON LIGHTING COLUMN BASES



CORROSION EVIDENT AROUND PROTECTIVE MEMBRANE UPSTAND ON LIGHTING COLUMN BASE.