

Main Cable Inspection. Hand-strand cable clamp / post connections. North Main Span. (West)				
Panel point.	Vertical movement. (sleeve wear-down)	Horizontal movement. (washer wear-down)	Washers missing.	Any other defect.
PP.46.	No.	Yes East (min)	No.	corrosion visible on face of upper cable band bolt heads.
PP.48.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.50.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.52.**	Yes. E & W. Bad.	Yes. E & W.(max)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.54.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.56.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.58.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.60.**	Yes. E & W. Bad.	Yes. E & W.(max)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.62.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.64.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.66.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (East)
PP.68.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.70.	No.	Yes West (min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.72.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.74.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.76.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.78.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.80.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.82.	(Slight) East.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (East)
PP.84.	No.	Yes West (min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.86.**	(Slight) East.	Yes West (min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.88.**	(Slight) East.	Yes West (max)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.90.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.92.	No.	Yes East (min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.94.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.96.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.98.	No.	Yes West (min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.100.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
Additional information. Main cable Sleeve . Slight gaps around perimeter seal of non hardening compound infill. (Thioflex.) Additional updated information. ***** Temporary hardwood wedges installed at locations highlighted with Asterix following the above inspection. 04/06/07.				



INSPECTION DEPARTMENT
MAIN CABLE INSPECTION. NORTH MAINSPAN (WEST)
DATE. 2007.