

Main Cable Inspection. Hand-strand cable clamp / post connections. North Side Span. ( West )				
Panel point.	Vertical movement. ( sleeve wear-down )	Horizontal movement. ( washer wear-down )	Washers missing.	Any other defect.
PP.00.	No.	No.	No.	corrosion visible on face of upper cable band bolt heads.
PP.02.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.04.	No.	Yes. West.(min)	No.	No.
PP.06.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.08.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.10.	(Slight ) West.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.12.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.14.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( east )
PP.16.	Yes. East.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.18.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.20.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.22.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.24.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.26.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.28.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.30.**	No.	Yes. E & W.(max)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.32.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.34.**	No.	Yes. E & W.(max)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.36.	Yes. E & W.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.38.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.40.	No.	Yes. East.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.42.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. ( west )
PP.44.	No.	Yes. East.(min)	No.	corrosion visible on face of upper cable band bolt heads.
Additional information.: Small area of paint missing on upper face of sleeve. Also small area of paint missing approx 1 mtr down from PP26. <b>Additional updated information.</b> ***** Temporary <b>hardwood</b> wedges installed at locations highlighted with <b>Asterix</b> following the above inspection. <b>05/06/07.</b>				