

Main Cable Inspection. Hand-strand cable clamp / post connections. South Side Span. (West.)				
Panel point.	Vertical movement. (sleeve wear-down)	Horizontal movement. (washer wear-down)	Washers missing.	Any other defect.
PP.00.	No.	No.	No.	No.
PP.02.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.04.	No.	Yes. East.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.06.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.08.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.10.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.12.	No.	No.	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.14.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (East)
PP.16.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (East)
PP.18.	No.	Yes. East.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.20.	No.	Yes. East.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.22.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.24.	(Slight) East.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.26.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.28.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.30.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.32.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.34.	No.	Yes. West.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.36.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.38.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.40.	(Slight) E & W.	Yes. E & W.(max)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.42.	No.	Yes. E & W.(min)	No.	Impact damage visible on face of upper cable band bolt. (west)
PP.44.	No.	No.	No.	corrosion visible on face of upper cable band bolt heads.
Additional information.: PP 42. Grommet missing upper face of hand strand horizontal connecting section to hand strand verticals. PP.04 Area of bare metal (corrosion evident) on main cable collar west face , north & south side. (probable trial siting for acoustic monitoring sensor)				

