

As requested by email dated 21<sup>st</sup> May 2009, the main span was inspected for any indication of structure elements being missing.  
Both "C" line walkways were walked from south main tower to mid span. Included in this "C" line walk the "D" line was observed from both east and west sides.  
Both "A" line walkways were walked from south main tower to mid span.  
Both top chord areas were observed from east and west footpaths.  
Centre grillage was also observed from the footpaths.

As a result of these inspections there were no indications of any elements being missing from the structure between the south tower and mid span.

Bridge Inspectors