



Missing bolt beam No 6 . on  
south face of cross girder  
PP71 (West. )



“ A line “ Tri-duct Expansion joint  
jubilee clips heavily corroded &  
broken , Require to be replaced on  
both E & W throughout Main-span  
PI. Area PP 68.5 to PP71.5.