


North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet

DATE: January 2015.

Colour code index to carriageway / cycle tracks (E & W) viaduct concrete defect description.



Concrete spalling evident.






Concrete repairs completed. (Under bearing replacement contract.)




Water Staining



North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet









North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet

DATE: January 2015.

NN






North




INSPECTION DEPARTMENT North Viaduct Carriageway &

North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet






North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet






North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet

DATE: January 2015.






North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet





North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet


DATE: January 2015.





North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet


DATE: January 2015.






North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet


DATE: January 2015.






North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet











North Viaduct Carriageway & cycle tracks (E & W.)Concrete Soffit Survey Sheet

