

FETA Maintenance - [Structure]

Copy Paste
Maint HAVS Report
Reports
File
OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016
ESM
Photo List
View Photos
View Plans
Structure List
Exit
08:20

Structure No: 7300
Location: EAST
Item: MAIN LINK
Criticality:

Element: SIDE SPAN NORTH
Part: N. MAIN TOWER
Inspection Freq: 6 Monthly
Vulnerability:

Record of Inspections

Inspector:
Date: 23/07/1997
Defects: NONE
Remarks:

Action Required: None
Works Completed: Yes

Record: 30 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)
Select Element and Defect

General Report

Input/Print General Report
Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:20

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 02/05/1995
Remarks:
Action Required: None Works Completed: Yes

Record: 29 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2/2 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:19

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Inspector: Defects: NONE
 Date: 08/09/1995
 Remarks:
 Action Required: None Works Completed: Yes

Record: 28 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:19

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector:
Date: 02/10/2000 Defects: NONE
Remarks:
Action Required Works Completed

Record: 27 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:18

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 20/03/2001
Remarks:
Action Required Works Completed

Record: 26 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste

Maint HAVS Report

Reports

File

OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

08:18

Structure No: 7300

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Inspector:

Date: 01/10/2001

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 25 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Print Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:17

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections Inspector: Date: 16/03/2006 Defects: NONE

Remarks:

Action Required Works Completed

Record: 14 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Print Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:17

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 23/10/2002
Remarks:
Action Required Works Completed

Record: 23 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Photos View Plans Structure List Exit

Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List 08:17

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections

Inspector: Defects: NONE
Date: 22/04/2003
Remarks:
Action Required Works Completed

Record: 22 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste

Maint HAVS Report

Reports

File

OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

08:16

Structure No: 7300

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Pait: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Inspector:

Date: 06/01/2004

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2/2 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:15

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Inspector: Defects: NONE
 Date: 30/08/2004
 Remarks:
 Action Required: Works Completed:

Record: 20 of 30

STRUCTURE REPORTS MENU

<p>Defect Reports</p> <p>Select Element (Complete List)</p> <p>Select Element and Defect</p>	<p>General Report</p> <p>Input/Print General Report</p> <p>Defects Report - this structure</p>
---	---

FETA Maintenance - [Structure]

Copy Paste ↕ ↕ ↕

Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

08:14

Structure No: 7300

Element: SIDE SPAN NORTH

Location: EAST

Part: N. MAIN TOWER

Item: MAIN LINK

Inspection Freq: 6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Inspector:

Date: 08/04/2005

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 19 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:13

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Inspector: Defects: NONE
 Date: 05/02/2008

Remarks:

Action Required: Works Completed:

Record: 18 of 30

STRUCTURE REPORTS MENU

<p>Defect Reports</p> <p>Select Element (Complete List)</p> <p>Select Element and Defect</p>	<p>General Report</p> <p>Input/Print General Report</p> <p>Defects Report - this structure</p>
---	---

FETA Maintenance - [Structure]

Copy Paste Z A Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:13

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE

Date: 06/11/2008

Remarks: *** General Information. **** New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Action Required Works Completed

Record: 17 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:12

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
 Date: 17/10/2007
 Remarks:
 Action Required Works Completed

Record: 16 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:12

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector:
Date: 19/08/2008 Defects: NONE
Remarks:
Action Required Works Completed

Record: 14 15 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List) 	Input/Print General Report
Select Element and Defect 	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste
Maint HAVS Report
Reports
File
OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016
ESM
Photo List
View Photos
View Plans
Structure List
Exit
08:11

Structure No: 7300
Location: EAST
Item: MAIN LINK
Criticality:

Element: SIDE SPAN NORTH
Part: N. MAIN TOWER
Inspection Freq: 6 Monthly
Vulnerability:

Record of Inspections
Inspector:
Date: 10/02/2005
Defects: NONE
Remarks:

Action Required
Works Completed

Record: 14 of 30

STRUCTURE REPORTS MENU

Defect Reports
Select Element (Complete List)
Select Element and Defect

General Report
Input/Print General Report
Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2/2 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:11

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 03/08/2005
Remarks:
Action Required Works Completed

Record: 13 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:10

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 09/02/2010
Remarks:
Action Required Works Completed

Record: 12 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste
Maint HAVS Report
Reports
File
OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016
ESM
Photo List
View Photos
View Plans
Structure List
Exit
08:10

Structure No: 7300
Location: EAST
Item: MAIN LINK
Criticality:

Element: SIDE SPAN NORTH
Part: N. MAIN TOWER
Inspection Freq: 6 Monthly
Vulnerability:

Record of Inspections
Inspector:
Date: 22/06/2010
Defects: NONE
Remarks:

Action Required
Works Completed

Record: 11 of 30

STRUCTURE REPORTS MENU

Defect Reports
Select Element (Complete List)
Select Element and Defect

General Report
Input/Print General Report
Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste
Maint HAVS Report
Reports
File
OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016
ESM
Photo List
View Photos
View Plans
Structure List
Exit
08:09

Structure No: 7300
Location: EAST
Item: MAIN LINK
Criticality:

Element: SIDE SPAN NORTH
Part: N. MAIN TOWER
Inspection Freq: 6 Monthly
Vulnerability:

Record of Inspections

Inspector:
Date: 11/02/2011
Defects: NONE
Remarks:

Action Required
Works Completed

Record: 10 of 30

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Z A Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:09

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 16/10/2011
Remarks:
Action Required Works Completed

Record: 9 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Z A Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:08

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 15/04/2016
Remarks:
Action Required Works Completed

Record: 8 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2/11 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:07

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 15/04/2013
Remarks:
Action Required Works Completed

Record: 7 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:07

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 18/10/2013
Remarks:
Action Required Works Completed

Record: 6 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2 1 15 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:06

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 28/03/2016
Remarks:
Action Required Works Completed

Record: 1 5 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Print Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:06

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Defects: NONE
Date: 16/02/2014
Remarks:
Action Required Works Completed

Record: 4 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste View Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:05

Structure No: 7300 Element: SIDE SPAN NORTH
 Location: EAST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Inspector: Defects: NONE
 Date: 07/07/2014
 Remarks:
 Action Required: Works Completed:

Record: 3 of 30

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:04

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Date: 26/02/2015 Defects: NONE
Remarks:
Action Required Works Completed

Record: 2 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure

FETA Maintenance - [Structure]

Copy Paste 2 1 2 1 Maint HAVS Report Reports File OfficeManager

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:02

Structure No: 7300 Element: SIDE SPAN NORTH
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections Inspector: Date: 25/08/2015 Defects: NONE
Remarks:
Action Required Works Completed

Record: 1 of 30

STRUCTURE REPORTS MENU

Defect Reports	General Report
Select Element (Complete List)	Input/Print General Report
Select Element and Defect	Defects Report - this structure