

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

06:59

Structure No: 7303

Location:

WEST



Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date:

08/09/1997

Inspector:

Defects:

NONE

Remarks:

Action Required

None

Works Completed

Yes

Record:

1

27

of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM Photo List



Structure List



08:58

Structure No: 7303

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 31/05/1995

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed: Yes

Record: 1 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:58

Structure No: 7303

Location:

WEST



Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly

Criticality:



Vulnerability:

Record of Inspections

Date:

29/11/1995

Inspector:

Defects:

NONE

Remarks:

Action Required

None



Works Completed

No Action

Record:



25

of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)



Input/Print General Report

Select Element and Defect



Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:57

Structure No: 7303



Element: MAIN SPAN

Location:

WEST



Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 28/08/2000

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 1 24 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:57

Structure No: 7303

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 28/03/2007

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 23 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:57

Structure No: 7303

Location:

WEST

MAIN LINK

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 22/10/2001

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 1 22 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:56

Structure No: 7303

Location:

WEST

MAIN LINK

Item:

Criticality:

Element: MAIN SPAN

Part:

N. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 10/04/2003

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14 21 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:55

Structure No: 7303

Location:

WEST

MAIN LINK

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 19/11/2002

Inspector:

Defects: NONE

Remarks:

Satisfactory At Time Of Inspection.

Action Required

Works Completed

Record: 1 20 21 22 23 24 25 26 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



08:55

Structure No: 7303

Location:

WEST



Element:

MAIN SPAN



Part:

N. MAIN TOWER



Item:

MAIN LINK



Inspection Freq:

6 Monthly



Criticality:



Vulnerability:



Record of Inspections

Date:

24/03/2006

Inspector:



Defects:

NONE



Remarks:

Action Required



Works Completed



Record:



19 of 27



<



111



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)



Input/Print General Report

Select Element and Defect



Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos View Plans



Structure List



Exit

08:55

Structure No:

7303



Element:

MAIN SPAN

Location:

WEST



Part:

N. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly



Criticality:



Vulnerability:



Record of Inspections

Date:

10/11/2006

Inspector:

Defects:

NONE



Remarks:

Action Required



Works Completed



Record:

18



of 27



11



11



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)



Input/Print General Report

Select Element and Defect



Defects Report - this structure

The Forth Road Bridge Maintenance Program

08:54

◀

Record: 17 of 27

STRUCTURE REPORTS MENU

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:54

Structure No: 7303

Location:

WEST



Element: MAIN SPAN

Part: N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 15/02/2005

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 16 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:54

Structure No: 7303

Location:

WEST

MAIN LINK

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 18/08/2005

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 15 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

08:53

Defects: NONE

NEW General Information. **REMOVED** New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Works Completed

Record: 14 of 27

STRUCTURE REPORTS MENU

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:53

Structure No: 7303

Location:

WEST



Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 26/02/2006

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 14 13 11 * PL of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:52

Structure No:

7303

Element:

MAIN SPAN

Location:

WEST

Part

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 01/10/2008

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 12 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos View Plans



Structure List



Exit

08:52

Structure No: 7303

Location:

WEST



Element: MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 29/05/2009

Inspector:

Defects: NONE

Remarks:

Action Required



Works Completed

Record: 11 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos View Plans



Structure List

Exit

08:51

Structure No: 7303

Location: WEST

Element: MAIN SPAN

Part: N. MAIN TOWER

Item: MAIN LINK

Inspection Freq: 6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 08/01/2016

Inspector: Defects: NONE

Remarks:

Action Required

Works Completed

Record: 10 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

08:50

Structure No: 7303

Location:

WEST



Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 18/07/2016

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 9 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

08:50

Structure No:

7303



Element:

MAIN SPAN

Location:

WEST



Part:

N. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly



Criticality:



Vulnerability:



Record of Inspections

Date:

05/05/2011

Inspector:

Luo



Defects:

NONE



Remarks:

Action Required



Works Completed



Record:



8



1.. of 27



tit



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Select Element and Defect

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos View Plans



Structure List



Exit

08:50

Structure No: 7303

Element: MAIN SPAN

Location:

WEST

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 14/12/2011

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 14 7 1 1. of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

08:49



◀

100

 McGraw-Hill

—

STRUCTURE REPORTS MENU

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:49

Structure No: 7303

Location:

WEST

MAIN LINK

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 01/02/2016

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 1 5 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:49

Structure No: 7303

Location: WEST

Item: MAIN LINK



Criticality:

Element: MAIN SPAN

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Date: 28/10/2016

Inspector:

Defects: NONE

Action Required:

Works Completed:

Record of Inspections

Record: 1 4 of 27

Remarks:

Structure Reports Menu

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

08:48

Structure No:

7303



Element:

MAIN SPAN

Location:

WEST



Part:

N. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly

Criticality:



Vulnerability:

Record of Inspections

Date:

25/04/2014

Inspector:

Defects:

GREASE-O-MATIC.

Remarks:

The Grease-O-Matic Supply Lines Fitted To The Main Link Have Become Detached From Their Firings To The Main Link. They Required To Be Re-Attached.

Action Required

Create Job Card

Works Completed

NO

Record:

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

The Forth Road Bridge Maintenance Program

08:48

STRUCTURE REPORTS MENU

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:47

Structure No:

7303

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

MAIN SPAN

Part:

N. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 19/05/2015

Inspector:

Defects: SEE PREVIOUS INSPECTION

Remarks:

The Grease-O-Matic Supply Lines Fitted To The Main Link Have Become Detached From Their Fixings To The Main Link. They Required To Be Re-Attached.

Action Required

No action reqd.

Works Completed

N/A

Record: 1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure