

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

11:06

Structure No: 7307

Element: SIDE SPAN SOUTH

Location:

WEST

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 29/05/1997

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed:

Yes

Record: 1 28 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:06

Structure No: 7307

Location:

WEST



Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 08/06/1998

Inspector:

Defects: NONE

Remarks:

Action Required: None



Works Completed

Yes

Record: 1 27 27 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:06

Structure No:

7307

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 13/06/2007

Inspector:

NONE

Defects:

Remarks:

Action Required

Works Completed

Record: 14



26



1. of 28

11

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:05

Structure No:

7307

Location:

WEST



Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Criticality:



Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date:

30/06/2001

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record:



25



1.. of 28



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

11:05

1001

Defects: NONE

12

Works Completed

Record: 1 24 of 28

STRUCTURE REPORTS MENU

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:04

Structure No: 7307

Location:

WEST



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 09/06/2002

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 23 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:04

Structure No: 7307

Location:

WEST



Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 03/12/2002

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 1 22 28 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:04

Structure No: 7307

Location:

WEST



Element: SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:



Vulnerability:



Record of Inspections

Date: 30/07/2008

Inspector:

Defects: NONE

Remarks:

Action Required



Works Completed



Record: 21 of 28



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:03

Structure No:

7307

Element:

SIDE SPAN SOUTH

Location:

WEST

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date:

13/04/2004

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record:

14

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

11:03

Structure No: 7307

Element: SIDE SPAN SOUTH

Location:

WEST

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 13/06/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 18 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:02

Structure No: 7307

Element: SIDE SPAN SOUTH

Location:

WEST

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 02/03/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14 17 21 25 29 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

11:02

Structure No: 7307

Location:

WEST



Element: SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly

Criticality:



Vulnerability:

Record of Inspections

Date: 18/12/2006

Inspector:

Defects: NONE

Remarks:

xxxx General Information, xxxxxx New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Action Required



Works Completed

Record:



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos

Structure
List

Exit

11:02

Structure No: 7307

Location:

WEST



Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly

Criticality:



Vulnerability:



Record of Inspections

Date: 21/11/2007

Inspector:



Defects:

NONE



Remarks:

Action Required



Works Completed



Record: 15 of 28



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)



Input/Print General Report

Select Element and Defect



Defects Report - this structure

The Forth Road Bridge Maintenance Program

ESM

Photo List



View Photos View Plans



View Plans

Structure List



Exit

11:01

Structure No: 7307

7307



Element: SIDE SPAN SOUTH

Location:

WEST

Part S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq: 6 Monthly

Criticality:

10

Vulnerability:

100

Record of Inspections

Inspector:

10

Date: 23/09/2008

23/09/2008

Defects:

NONE

Remarks:

Action Required

Works Completed

10

Record: 14 of 28

of 28

111

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

11:01

Structure No: 7307

Location:

WEST

MAIN LINK

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Criticality:

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record of Inspections

Date: 17/03/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14

13

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos

View Plans

Structure List

Exit

11:01

Structure No: 7307

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 26/08/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 12 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

11:00

Structure No:

7307

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 16/02/2016

Inspector:

Defects:

NONE

Remarks:

Action Required

Works Completed

Record: 11 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program


19/02/2016

ESM

Photo List



Structure List



Exit

11:00

Structure No: 7307

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 20/08/2016

Inspector: [Name]

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 10 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

11:00

Structure No: 7307



Element: SIDE SPAN SOUTH

Location:

WEST



Part:

S. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly



Criticality:



Vulnerability:



Record of Inspections

Date: 03/03/2011

Inspector:



Defects:

NONE



Remarks:

Action Required



Works Completed



Record: 14



9 of 28



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)



Input/Print General Report

Select Element and Defect



Defects Report - this structure

The Forth Road Bridge Maintenance Program

10:59

Vulnerability:

NONE

Works Completed

Record: 1 3 of 28

STRUCTURE REPORTS MENU

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:59

Structure No: 7307

Location:

WEST

MAIN LINK

Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 08/05/2012

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 1 7 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:59

Structure No: 7307

Location:

WEST



Element: SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly

Criticality:



Vulnerability:



Record of Inspections

Date: 20/11/2012

Inspector:

Defects: NONE



Remarks:

Action Required



Works Completed



Record:



6 of 28



tit



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos View Plans



Structure List



Exit

10:58

Structure No: 7307

Location:

WEST

Item:

MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 09/05/2013

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 5 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



10:58

Structure No: 7307

Location:

WEST



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Item:

MAIN LINK



Inspection Freq:

6 Monthly



Criticality:



Vulnerability:



Record of Inspections

Date:

17/02/2014

Inspector:

Defects:

NONE



Remarks:

Action Required



Works Completed



Record:



4



PL

of 28



tit



STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:58

Structure No:

7307

Element:

SIDE SPAN SOUTH

Location:

WEST

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Date: 01/08/2014

Inspector:

GREASE-O-MATIC

Remarks:

Main Link Grease-O-Matic Cartridge Supply Line Connection To Top Pin On The (East Side)
) Has Become Disconnected , Requires To Be Reitted.

Action Required

Create Job Card

Works Completed

NO

Record: 1 3 of 28

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos



View Plans

Structure
List

Exit

10:57

Structure No:

7307

Location:

WEST

Item:

MAIN LINK

Criticality:



Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 09/03/2016

Inspector:

1 071

Defects:

SEE PREVIOUS INSPECTION

Remarks:

Please Refer To Inspection Date : 01/08/2014, For Information.

Action Required

No action reqd.

Works Completed

N/A

Record:

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo
List

View Photos

View Plans

Structure
List

Exit

10:57

Structure No:

7307

Location:

WEST

Item:

MAIN LINK

Criticality:

Element:

SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Inspection Freq:

6 Monthly

Vulnerability:

Record of Inspections

Date: 08/10/2015

Inspector:

Defects: SEE PREVIOUS INSPECTION

Remarks:

Please Refer To Inspection Date : 01/08/2014. For Information.

Action Required

No action reqd.

Works Completed

N/A

Record: 1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

1

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure