

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:08

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

Record:  1  of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:11

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections



Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

Record:  2  of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:12

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="25/05/2014"/>	Inspector:	<input type="text"/>
		Defects:	<input type="text" value="NONE"/>

Remarks:

Action Required	<input type="text"/>	Works Completed	<input type="text"/>
-----------------	----------------------	-----------------	----------------------

Record: of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:13

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Inspector:

Date:

Defects:

Remarks:

Action Required

Works Completed

Record:  4  of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:14

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required Works Completed

Record: 5 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:15

Structure No: 7302  Element: MAIN SPAN
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections

Inspector: 

Date: 24/06/2012

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 6 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:16

Structure No:  Element:
Location: Part:
Item: Inspection Freq:
Criticality: Vulnerability:

Record of Inspections

Date: Inspector:
Defects:

Remarks:

Action Required: Works Completed:

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:17

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="05/05/2011"/>	Inspector:	<input type="text"/>
Remarks:	<input type="text"/>	Defects:	<input type="text" value="NONE"/>
Action Required	<input type="text"/>	Works Completed	<input type="text"/>

Record: 8 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

 View Photos

 View Plans

Structure List

 Exit

10:18

Structure No:  Element:

Location: Part:

Item: Inspection Freq:

Criticality: Vulnerability:


Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required: Works Completed:

Record:  9 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:22

Structure No:  Element:

Location: Part:

Item: Inspection Freq:

Criticality: Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required Works Completed

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:23

Structure No:

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

Record: of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:24

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:24

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

 View Photos

 View Plans

Structure List



 Exit

10:25

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="18/05/2007"/>	Inspector:	<input type="text"/>
Remarks:	<input type="text" value="*** General Information. **** New Gravity Fed Lubrication System Installed At Main Link. Old System Removed."/>		
Defects:	<input type="text" value="NONE"/>	Action Required:	<input type="text"/>
		Works Completed:	<input type="text"/>

Record:  14  of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

 View Photos

 View Plans

Structure List

 Exit

10:26

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="18/08/2005"/>	Inspector:	<input type="text"/>
		Defects:	<input type="text" value="NONE"/>

Remarks:

Action Required	<input type="text"/>	Works Completed	<input type="text"/>
-----------------	----------------------	-----------------	----------------------

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

 View Photos

 View Plans

Structure List

 Exit

10:27

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required: Works Completed:

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:27

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

Record:  17 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:28

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections



Date: Inspector:

Defects:

Remarks:

Action Required

Works Completed

Record:  18  of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

 View Photos

 View Plans

Structure List

 Exit

10:30

Structure No:

7302



Element:

MAIN SPAN

Location:

EAST

Part:

N. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

Record of Inspections

Inspector:

Date:

24/06/2008

Defects:

NONE

Remarks:

Empty text area for remarks.

Action Required

Works Completed

Record: 19 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:32

Structure No:	<input type="text" value="7302"/>	Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>	Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>	Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>	Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="06/11/2002"/>	Inspector:	<input type="text"/>
Remarks:	<input type="text" value="Satisfactory At Time Of Inspection."/>		
Defects:	<input type="text" value="NONE"/>	Action Required:	<input type="text"/>
		Works Completed:	<input type="text"/>

Record: 20 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:33

Structure No:	<input type="text" value="7302"/>	Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>	Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>	Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>	Vulnerability:	<input type="text"/>

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required: Works Completed:

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:34

Structure No:	<input type="text" value="7302"/>		Element:	<input type="text" value="MAIN SPAN"/>
Location:	<input type="text" value="EAST"/>		Part:	<input type="text" value="N. MAIN TOWER"/>
Item:	<input type="text" value="MAIN LINK"/>		Inspection Freq:	<input type="text" value="6 Monthly"/>
Criticality:	<input type="text"/>		Vulnerability:	<input type="text"/>

Record of Inspections

Date:	<input type="text" value="22/10/2001"/>	Inspector:	<input type="text"/>
Remarks:	<input type="text"/>		
Defects:	<input type="text" value="NONE"/>	Action Required:	<input type="text"/>
		Works Completed:	<input type="text"/>

Record: 22 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:35

Structure No: 

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Date: Inspector:

Defects:

Remarks:

Action Required Works Completed

Record: 23 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans


Structure List

Exit

10:36

Structure No: 7302  Element: MAIN SPAN
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections

Inspector: 

Date: 28/08/2000

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 24 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:40

Structure No: 7302  Element: MAIN SPAN
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections

Inspector:  Defects: NONE
Date: 29/11/1999
Remarks:
Action Required: None Works Completed: No Action

Record: 25 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:41

Structure No:

Location:

Item:

Criticality:

Element:

Part:

Inspection Freq:

Vulnerability:

Record of Inspections

Inspector:

Date:

Defects:

Remarks:

Action Required

Works Completed

Record: of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

18/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:44

Structure No: 7302  Element: MAIN SPAN
Location: EAST Part: N. MAIN TOWER
Item: MAIN LINK Inspection Freq: 6 Monthly
Criticality: Vulnerability:

Record of Inspections

Inspector:  Defects: NONE
Date: 08/09/1997
Remarks:
Action Required: None Works Completed: Yes

Record: 27 of 27

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure