

SIDE TOWER POST TENSION CABLE SURVEY	
SOUTH SIDE TOWER	EAST LEG BASE LEVEL
WEST 1 2 3	4 5 6 7 8 9 10
	NORTH
EAST 1 2 3	4 5 6 7 8 9 10
E1 HEAVY CORROSION	W1 HEAVY CORROSION
E2 HEAVY CORROSION	W2 HEAVY CORROSION
E3 HEAVY CORROSION	W3 HEAVY CORROSION
E4 ALL STANDS SEVERED	W4 HEAVY CORROSION
E5 ALL STANDS SEVERED	W5 ALL STANDS SEVERED
E6 HEAVY CORROSION E7 ALL STANDS SEVERED	W6 ALL STANDS SEVERED W7 HEAVY CORROSION
E8 5 in No severed	W8 HEAVY CORROSION
E9 10 in No severed	W9 HEAVY CORROSION
E10 HEAVY CORROSION	W10 HEAVY CORROSION
Some patches of dampness on floor at time of inspection. Small sump at base level full at time of inspection. No further breakages since previous inspection carried out. 17/05/12.	
INSPECTOR:	DATE: 2013.04.12.
INSPECTOR:	DATE: 2013.04.12.