

## South Viaduct Principal Inspection, September 2009.

### Report index.

- Front Cover.
- Report index.
- General Report.
- Inspection Record Sheets, VSPI. 01 to VSPI. 11.
- Relevant viaduct soffit defect survey sheets.
- Box girder access permanent staging survey sheet.
- Photographs: roller & pin Bearings.
- Photographs: Paint breakdown areas.
- Photographs: New drop down handrail / edge protection at pier S 3.
- Photographs: New drop down handrail / edge protection at box girder access hatch permanent staging.
- Photographs: Redundant & defective box girder platforms.
- Photographs: Lighting columns.



