



| |
|------------------------|
| INSPECTION DEPARTMENT |
| South west box girder. |
| DATE. 28/09/12. |

Cable tray support on West face of South West box girder with temporary rope.
Locations as per list.



Outrigger beams.

Section box.

97/100.
113/115.
125.
128/130.
139/141.
152/153.
163/165.
171.
175/177.
187/189.
199/201.
210/211.

24.
28.
31.
32.
34.
37.
40.
42.
43.
46.
49.
52.



| |
|------------------------|
| INSPECTION DEPARTMENT |
| South west box girder. |
| DATE. 28/09/12. |



Located Between Outrigger Beams 104/105 in section box No 26, There Are What Appear To Be Redundant Cables Coming Through The East Face Of The Box Girder.



Electric Cable Coming Through A Conduit Located On The Ceiling Of The Box Girder located section box 32.



| |
|------------------------|
| INSPECTION DEPARTMENT |
| South west box girder. |
| DATE. 28/09/12. |



Located At Outrigger Beam 151 On The North Side Of S5 There Is Water Lying In The Second Floor Section. Evidence Of Dampness Around The Seal In The Socket Of The Carriageway Rainwater Downpipe Running Through The Box Girder.



Photographs showing cable tray, unistrut, lighting boxes located in section boxes, for use in electrical program of works or removal.
?

Following completion of electrical programme of works, box girders will be cleaned and all surplus materials and debris removed by general operatives.



| |
|------------------------|
| INSPECTION DEPARTMENT |
| South west box girder. |
| DATE. 28/09/12. |