

| SIDE TOWER POST TENSION CABLE SURVEY | | | | |
|--|---------|--------------|-------------------|-------|
| SOUTH SIDE TOWER | WES | ST LEG | BASE LE | EVEL |
| WEST | | 5 6 7 8 | 9 10 | |
| | 1 2 3 4 | <u> </u> | | NORTH |
| | | | | |
| EAST | 1 2 3 4 | 5 6 7 8 | 9 10 | |
| E1 1 OFF STRAND SEVERED. W1 HEAVY CORROSION. | | | | |
| | | | CORROSION. | |
| E21 OFF STRAND SEVERED.E3HEAVY CORROSION. | | | <u>CORROSION.</u> | |
| E3 HEAVY CORROSION. E4 HEAVY CORROSION. | | - | CORROSION. | |
| E5 HEAVY CORROSION. | | | CORROSION. | |
| E6 HEAVY CORROSIC | | | CORROSION. | |
| E7 HEAVY CORROSIC | | - | CORROSION. | |
| E8 HEAVY CORROSIC | | | CORROSION. | |
| E9 HEAVY CORROSIC | DN. | W9 HEAV | CORROSION. | |
| E10 HEAVY CORROSIC | DN. | W10 HEAV | CORROSION. | |
| Floor dry at time of inspection. Dampness moisture evident at post tension cable bases. | | | | |
| INSPECTOR: | | DATE: 27/05/ | | |
| INSPECTOR: | | DATE: 27/05/ | 11 | |