





| INSPECTION DEPARTMENT |
|--|
| Trough defects. South East & West main-span. |
| DATE. 12/06/12. |

South East


Between PP.70-71 . Weld crack Trough No 2 . approx 100mm long.




Between PP.70-71 . Weld crack Trough No 2. approx 250 mm long.



Between PP. 75-76. Weld crack Trough No 1 . approx 50 mm long.



Between PP.83-84. Weld crack , Trough No 2 . approx 75 mm long.






| INSPECTION DEPARTMENT |
|--|
| Trough defects. South East & West main-span. |
| DATE. 12/06/12. |

South West

Between PP.55-56. Weld crack , Trough No 2 . approx 100 mm long.



ALL OF THE ABOVE DEFECTIVE TROUGH WELD LOCATIONS REQUIRE ACCESS PLATFORMS FROM “B” TO “C” LINE.