



INSPECTION DEPARTMENT

South viaduct external inspection. (unused platform steelwork DATE. 09/09/09



Unused box girder access/egress platform steelwork located between box girder sections 44/45 (west) between crossbeams 180/182.



Unused box girder access/egress platform steelwork located between box girder sections 44/45 (west) between crossbeams 180/182.

Created by GE. C:\Users\136377\Desktop\FETA inspection records of approach Viaducts\South\Principle Inspections\South Viaduct External PI 2009\Unused Platform Steelwork..doc





Created by GE. C:Users136377DesktopFETA inspection records of approach

Steelwork..doc

Viaducts\South\Principle Inspections\South Viaduct External PI 2009\Unused Platform

INSPECTION DEPARTMENT

South viaduct external inspection. (unused platform steelwork DATE. 09/09/09