

INSPECTION DEPARTMENT

Viaduct Soffit Survey Sheet

DATE: January 2015

Colour code index to defect description.



Concrete spalling evident.



Concrete missing. / Re-bar exposed heavy corrosion evident.



Concrete repairs completed. (Under bearing replacement contract.)



Water staining