

During the course of the weekly Demag topside inspection, it was found that there are cracks to west side of SE2 tongue plate.



What is not shown in the above picture is how much the plate deflects upwards.

Bridge Inspectors: