



INSPECTION DEPARTMENT

"A" Line <u>East</u> Main Span Engineer Defects

DATE: 06.12.09



P.P.59 N.E.

Ist DUCT HANGER SOUTH OF P.P. LINDAPTOR AND HANGER LOOSE.

(NOT BEARING WEIGHT)