



INSPECTION DEPARTMENT

"A" Line WEST Main Span Painter Defects DATE: 08/12/09



P.P.93 S.W. (IST BEAM NORTH OF P.P.) PAINT DAMAGE



<u>P.P.96 S.W.</u>

PAINT DAMAGE



EXAMPLE OF ALL HANGERS THAT HAVE BEEN TIGHTENED. ALL HAVE DAMAGE TO PAINTWORK FROM HEAT. NUMEROUS LOCATION ALONG "A" LINE





INSPECTION DEPARTMENT "A" Line WEST Main Span Painter Defects DATE: 08/12/09

<u>68</u> 08/12/2009

<u>P.P. 68 N.W.</u> UPPER-FRONT MISSED MARKED UP AREAS



P.P. 65 N.W. LAST UPPER FRONT

EXAMPLE OF TOUCHED UP AREAS SHOWING SIGNS OF BREAKDOWN