

Billet Survey Main Span (East)

DATE. 2013.08.15

North East Main Span:

- PP 48 Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 showing signs of wear Noisy
- PP 50 Stringer nos. 1-3 packers missing, stringer no. 4 packer in place Noisy 2 no sheared bolts on 4, east face.
- PP 52 All stringers ok with packers in place, satisfactory quiet
- PP 54 Stringer nos. 1-4 packers missing Noisy
- PP 56 Stringer nos. 1 & 3 packers missing, stringer nos. 2 packer showing signs of wear, stringer no. 4 packer in place **Noisy**
- PP 58 Stringer nos. 1 & 2 missing, stringer nos. 3 & 4 packers in place Noisy
- PP 60 All stringers ok with packers in place, satisfactory quiet.
- PP 62 All stringers ok with packers in place, satisfactory quiet.
- PP 64 All stringers ok with packers in place, satisfactory quiet.
- PP 66 All stringers ok with packers in place, satisfactory quiet
- PP 68 Stringer no. 2 packer missing, stringer nos. 1, 3 & 4 showing signs of wear Noisy
- PP 70 All stringers ok with packers in place, satisfactory quiet.
- PP 72 All stringers ok with packers in place, satisfactory quiet
- PP 74 All stringers ok with packers in place, satisfactory quiet
- PP 76 All stringers ok with packers in place, satisfactory quiet.
- PP 78 All stringers ok with packers in place, satisfactory quiet.
- PP 80 Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place Noisy
- PP 82 Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers showing signs of wear Noisy
- PP 84 All stringers ok with packers in place, satisfactory quiet
- PP 86 All stringers ok with packers in place, satisfactory quiet
- PP 88 Stringer nos. 1 & 2 packers missing, stringer no. 3 packer showing signs of wear, stringer no. 4 packer in place **Noisy**Bolt missing on 1, east face

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet survey August 2013\Billet Survey - East Main Span 2013.08.15.doc



Billet Survey Main Span (East)

DATE. 2013.08.15

North East Main Span cont....:

- PP 90 Stringer nos. 1 & 2 missing, stringer nos. 3 & 4 packers in place Noisy
- PP 92 Stringer nos. 1-3 packers missing, stringer no. 4 packer showing signs of wear Noisy
- PP 94 Stringer nos. 1-3 packers showing signs of wear, stringer no. 4 packer in place Noisy
- PP 96 Stringer no. 1 packer in place, stringer nos. 2-4 packers showing signs of wear monitor
- PP 98 All stringers ok with packers in place, satisfactory quiet
- PP 100 All stringers ok with packers in place, satisfactory quiet

South East Main Span:

- PP 48 All stringers ok with packers in place, satisfactory quiet
- PP 50 Stringer nos. 1-3 showing signs of wear, stringer no. 4 packer in place monitor
- PP 52 Stringer nos. 1-3 showing signs of wear, stringer no. 4 packer in place monitor
- PP 54 All stringers ok with packers in place, satisfactory quiet
- PP 56 All stringers ok with packers in place, satisfactory quiet
- PP 58 All stringers ok with packers in place, satisfactory quiet
- PP 60 All stringers ok with packers in place, satisfactory quiet
- PP 62 Stringer nos. 1-3 showing signs of wear, stringer no. 4 packer in place monitor
- PP 64 Stringer no. 1 packer missing, stringer no. 2 showing signs of wear, stringer nos. 3 & 4 packers in place monitor
- PP 66 Stringer nos. 1 & 2 packers showing signs of wear, stringer nos. 3 & 4 packers in place quiet
- PP 68 All stringers ok with packers in place, satisfactory quiet

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet survey August 2013\Billet Survey - East Main Span 2013.08.15.doc





Billet Survey Main Span (East)

DATE. 2013.08.15

South East Main Span cont....:

- PP 70 All stringers ok with packers in place, satisfactory quiet
- PP 72 Stringer nos. 1 & 2 showing signs of wear, stringer nos. 3 & 4 packers in place quiet
- PP 74 All stringers ok with packers in place, satisfactory quiet
- PP 76 Stringer nos. 1 & 2 showing signs of wear, stringer nos. 3 & 4 packer in place monitor
- PP 78 Stringer nos. 1 & 2 packers missing, stringer nos. 3 & 4 packers in place monitor
- PP 80 Stringer nos. 1 4 showing signs of wear Noisy
- PP 82 All stringers ok with packers in place, satisfactory quiet
- PP 84 All stringers ok with packers in place, satisfactory quiet
- PP 86 Stringer nos. 1 & 2 packers showing signs of wear, stringer nos. 3 & 4 packers in place monitor
- PP 88 Stringer nos. 1 4 packers showing signs of wear Noisy
- PP 90 Stringer nos. 1 3 packers missing, stringer no. 4 packer showing signs of wear Noisy
- PP 92 Stringer nos. 1 4 packers showing signs of wear Noisy
- PP 94 Stringer nos. 1-4 showing signs of wear monitor
- PP 96 All stringers ok with packers in place, satisfactory quiet
- PP 98 Stringer no. 1 packer missing, stringer nos. 2-4 packers showing signs of wear Noisy
- PP 100 Stringer nos. 1-4 packers showing signs of wear quiet