



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.08.15

North West Main Span:

- PP 48 - Stinger no. 1 packer missing, stinger nos. 2-4 ok with packers in place, - **monitor**
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - Stinger nos. 1, 2 & 3 packers missing. Stinger no. 4 ok – **Noisy**
- PP 56 - Stinger no. 1 packer showing signs of wear. Stinger nos. 2, 3 & 4 ok - quiet
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - Ok – this was replaced as part of the half joint trial that was undertaken by Raynesway.
- PP 62 - Stringers 1 packer missing, stinger nos. 2 & 3 showing signs of wear. Stinger no. 4 ok - **Noisy**
- PP 64 - Stinger nos. 1 & 2 packers missing. Stinger nos. 3 & 4 showing signs of wear **Noisy**
- PP 66 - All stringers ok with packers in place, satisfactory - quiet
- PP 68 - All stringers ok with packers in place, satisfactory - quiet
- PP 70 - Stinger nos. 1 - 4 packers showing signs of wear. – **Noisy**
- PP 72 - All stringers ok with packers in place, satisfactory - quiet
- PP 74 - All stringers ok with packers in place, satisfactory - quiet
- PP 76 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 78 - Stinger nos. 1 & 2 packers showing signs of wear. Stringers 3 & 4 ok – **Noisy**
- PP 80 - All stringers ok with packers in place, satisfactory - quiet
- PP 82 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 84 - Stringers 1-2 packers showing signs of wear , stinger nos. 3-4 packers in place, satisfactory- quiet
- PP 86 - All stringers ok with packers in place, satisfactory - quiet
- PP 88 - Stinger no. 1 packer missing, stinger nos. 2- 4 packers worn. **Noisy**



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.08.15

PP 90 - Stringer no. 1 packer showing signs of wear, stringer nos. 2-3 satisfactory, stringer no. 4 showing signs of wear, satisfactory - [monitor](#)

North West Main Span cont.....:

- PP 92 - Stringer nos. 1 - 3 packers missing. Stringer showing signs of wear – **Noisy**
- PP 94 - All stringers ok with packers in place, satisfactory - quiet
- PP 96 - Stringer no. 1 - 4 packers showing signs of wear – **Noisy**
- PP 98 - All stringers ok with packers in place, satisfactory - quiet
- PP 100 - All stringers ok with packers in place but showing slight signs of wear – [monitor](#)

South West Main Span:

- PP 48 - Stringer no. 1-2 packers showing signs of wear, stringer no. 3-4 packers satisfactory - [monitor](#)
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
Stringer no. 3 has a sheared bolt on the east face
- PP 52 - Stringer nos. 1 through to 4 packers worn – **Noisy**
- PP 54 - Stringer nos. 1 through to 4 packers worn – **Noisy**
- PP 56 - All stringers ok with packers in place, satisfactory - quiet
- PP 58 - Stringer nos. 1 & 3 packer showing signs of wear, stringer no. 2 packer missing, stringer no. 4 satisfactory - **Noisy**
- PP 60 - Stringer nos. 1-3 packers missing, stringer no. 4 packer in place - **Noisy**
- PP 62 - Stringer nos. 1-4 packers missing - **Noisy**
- PP 64 - All stringers ok with packers in place, satisfactory - quiet
- PP 66 - Stringer nos. 1, 3 & 4 packers in place, stringer no. 2 packer missing - [monitor](#)

G:\dd\t&p\rmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet survey August 2013\Billet Survey - West Main Span 2013.08.15.doc



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.08.15

PP 68 - All stringers ok with packers in place, satisfactory - quiet

South Main Span cont....:

PP 70 - All stringers ok with packers in place, satisfactory - quiet

PP 72 - Stringer no. 1 packer missing, stringer no. 2 packer showing signs of wear, stringer nos. 3-4 packers in place - **monitor**

PP 74 - Stringer nos. 1 & 2 packers worn. Stringer nos. 3 & 4 ok – **Noisy**

PP 76 - All stringers ok with packers in place, satisfactory - quiet

PP 78 - All stringers ok with packers in place, satisfactory - quiet

PP 80 - Stringer nos. 1 through to 4 packers missing – **Noisy**

PP 82 - Stringer nos. 2 & 3 packers missing. Stringer nos. 1 & 4 ok – **Noisy**

PP 84 - Stringer nos. 2 & 4 packers showing signs of wear. Stringer nos. 1, 3 ok – **monitor**
bolt missing on 4 west face.

PP 86 - All stringers ok with packers in place, satisfactory - quiet

PP 88 - All stringers ok with packers in place, satisfactory - quiet

PP 90 - All stringers ok with packers in place, satisfactory - quiet

PP 92 - Stringer nos. 1 & 3 packers missing. Stringer no. 4 ok – **Noisy**

PP 94 - All stringers ok with packers in place, satisfactory - quiet

PP 96 - All stringers ok with packers in place, satisfactory - quiet

PP 98 - Stringer nos 1 & 3 packers in place, stringer nos. 2 & 4 packers missing - **Noisy**

PP 100 - All stringers ok with packers in place, satisfactory - quiet