



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2014.03.25

North West Main Span:

- PP 48 - Stringer no. 1 packer missing, stringer nos. 2-4 showing signs of wear - [monitor](#)
- PP 50 - Stringer no. 1 packer missing, stringer nos 2-4 all packers in place, satisfactory - quiet
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - All stringers ok with packers in place, satisfactory - quiet
- PP 56 - Stringer no. 1 packer showing signs of wear. Stringer nos. 2, 3 & 4 packers in place, satisfactory - quiet
- PP 58 - Stringer nos. 1-3 all packers in place, stringer no. 4 showing signs of wear, satisfactory - quiet
- PP 60 - This was replaced as part of the half joint trial that was undertaken by Raynesway, monthly report done reporting condition.
- PP 62 - All stringers ok with packers in place, satisfactory - quiet
- PP 64 - All stringers ok with packers in place, satisfactory - quiet
- PP 66 - All stringers ok with packers in place, satisfactory - quiet
- PP 68 - All stringers ok with packers in place, satisfactory - quiet
- PP 70 - Stringer nos. 1 packer missing, stringer nos. 2 – 4 all packers showing signs of wear, – **Noisy**
- PP 72 - Stringer no. 1 packer missing, stringer no. 2 packer showing signs of wear, stringer nos. 3-4 all packers in place - [monitor](#)
- PP 74 - All stringers ok with packers in place, satisfactory - quiet
- PP 76 - All stringers ok with packers in place but showing slight signs of wear – [monitor](#)
- PP 78 - Stringer nos. 1 & 2 packers showing signs of wear. Stringers 3 & 4 all packers in place – **Noisy**
- PP 80 - Stringer nos 1-2 showing signs of wear, stringer nos. 3-4 all packers in place - [monitor](#)
- PP 82 - All stringers ok with packers in place but showing signs of wear – [monitor](#)
- PP 84 - Stringer nos. 1-3 packers showing signs of wear , stringer no.4 packer in place, satisfactory- quiet



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2014.03.25

North West Main Span cont.....:

- PP 86 - All stringers ok with packers in place, satisfactory - quiet
- PP 88 - All stringers ok with packers in place, satisfactory - quiet.
- PP 90 - Stringer nos. 1-4 all packers showing signs of wear - **Noisy**
- PP 92 - All stringers ok with packers in place, satisfactory - quiet
- PP 94 - Stringer no. 1 showing sings of wear, stringers 2-4 packers in place, satisfactory - quiet
- PP 96 - All stringers ok with packers in place, satisfactory – quiet
- PP 98 - All stringers ok with packers in place, satisfactory - quiet
- PP 100 - All stringers ok with packers in place, satisfactory - quiet

South West Main Span:

- PP 48 - Stringer nos. 1-4 all packers showing signs of wear - **Noisy**
- PP 50 - Stringer nos 1 & 4 packers in place, satisfactory, stringer nos. 2 & 3 showing signs of wear - quiet
[Billet no. 3 has 1no. sheared bolt on the west face and 1 no. sheared bolt on the east face](#)
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - Stringer nos. 1-4 all packers missing – **Noisy**
- PP 56 - All stringers ok with packers in place, satisfactory - quiet
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - Stringer nos. 1, 2 & 4 ok with packers in place, stringer no. 3 packer missing - quiet
- PP 62 - All stringers ok with packers in place, satisfactory - quiet
- PP 64 - Stringer no. 1 packer missing, stringer no. 2 packer showing signs of wear, stringer nos. 3-4 packers in place - **Noisy**

G:\dd\t&p\rmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\Billet Survey March 2014\Billet Survey West Main Span 2014.03.25.doc



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2014.03.25

PP 66 - Stringer nos. 1, 3 & 4 all packers in place, stringer no. 2 packer missing - **monitor**

PP 68 - All stringers ok with packers in place, satisfactory – quiet

South Main Span cont....:

PP 70 - Stringer nos 1-3 all packers missing, stringer no. 4 packer in place - **Noisy**

PP 72 - Stringer nos. 1-2 all packers missing, stringer nos. 3-4 packers in place - **Noisy**

PP 74 - Stringer nos. 1-2 all packers missing, stringer nos. 3-4 showing signs of wear - **Noisy**

PP 76 - Stringer no. 1 packer showing signs of wear, stringer nos. 2-3 packers missing, stringer no. 4 packer in place - **Noisy**

PP 78 - Stringer nos. 1-4 all packers showing signs of wear - **Noisy**

PP 80 - All stringers ok with packers in place, satisfactory - quiet

PP 82 - All stringers of with packers in place, satisfactory - quiet

PP 84 - Stringer no. 1 packer in place, stringer no. 2 packer showing signs of wear, stringer nos. 3-4 all packers in place, satisfactory - quiet

PP 86 - All stringers ok with packers in place, satisfactory - quiet

PP 88 - All stringers ok with packers in place, satisfactory - quiet

PP 90 - Stringer no. 1 packer missing, stringer nos. 2-4 satisfactory – **Noisy**
Stringer no. 1 bolt sheared on east face

PP 92 - All stringers ok with packers in place, satisfactory - quiet

PP 94 - Stringer no. 1 packer showing signs of wear, stringer nos. 2-4 all packers in place, satisfactory - quiet

PP 96 - All stringers ok with packers in place, satisfactory - quiet

PP 98 - All stringers ok with packers in place, satisfactory - quiet

PP 100 – Stringer no. 1 showing signs of wear, stringer nos. 2-4 all packers in place, satisfactory - quiet