



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.11.21

North West Main Span:

- PP 48 - Stinger no. 1 packer missing, stinger nos. 2-4 ok with packers in place, - **monitor**
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - All stringers ok with packers in place, satisfactory - quiet
- PP 56 - Stinger no. 1 packer showing signs of wear. Stinger nos. 2, 3 & 4 ok - quiet
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - Ok – this was replaced as part of the half joint trial that was undertaken by Raynesway.
- PP 62 - Stinger no. 1 packer missing, stinger nos. 2 -4 showing signs of wear - **Noisy**
- PP 64 - Stinger nos. 1 & 2 packers missing. Stinger nos. 3 & 4 showing signs of wear
Noisy
- PP 66 - All stringers ok with packers in place, satisfactory - quiet
- PP 68 - All stringers ok with packers in place, satisfactory - quiet
- PP 70 - Stinger nos. 1 - 4 packers showing signs of wear. – **Noisy**
- PP 72 - All stringers ok with packers in place, satisfactory - quiet
- PP 74 - All stringers ok with packers in place, satisfactory - quiet
- PP 76 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 78 - Stinger nos. 1 & 2 packers showing signs of wear. Stringers 3 & 4 ok – **Noisy**
- PP 80 - All stringers ok with packers in place, satisfactory - quiet
- PP 82 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 84 - Stringers 1-2 packers showing signs of wear , stinger nos. 3-4 packers in place,
satisfactory- quiet
- PP 86 - All stringers ok with packers in place, satisfactory - quiet
- PP 88 - Stinger no. 1 packer missing, stinger nos. 2- 4 packers worn. **Noisy**
- PP 90 - Stinger no. 1 packer showing signs of wear, stinger nos. 2-3 satisfactory, stinger no.
4 showing signs of wear, satisfactory - **monitor**



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.11.21

North West Main Span cont.....:

- PP 92 - Stringer nos. 1 - 3 packers missing. Stringer 4 showing signs of wear – **Noisy**
- PP 94 - Stringer no. 1 showing signs of wear, stringers 2-4 packers in place, satisfactory - quiet
- PP 96 - Stringer no. 1 - 4 packers showing signs of wear – **Noisy**
- PP 98 - All stringers ok with packers in place, satisfactory - quiet
- PP 100 - All stringers ok with packers in place but showing slight signs of wear – **monitor**

South West Main Span:

- PP 48 - Stringer no. 1-2 packers showing signs of wear, stringer no. 3-4 packers satisfactory - **monitor**
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
Billet no. 3 has a sheared bolt on the west face
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - Stringer nos. 1 through to 4 packers missing – **Noisy**
- PP 56 - All stringers ok with packers in place, satisfactory - quiet
- PP 58 - Stringer nos. 1 - 3 packer missing, stringer no. 4 packer ok - **Noisy**
- PP 60 - All stringers ok with packers in place, satisfactory - quiet
- PP 62 - Stringer nos. 1-4 packers missing - **Noisy**
- PP 64 - All stringers ok with packers in place, satisfactory - quiet
- PP 66 - Stringer nos. 1, 3 & 4 packers in place, stringer no. 2 packer missing - **monitor**
- PP 68 - All stringers ok with packers in place, satisfactory - quiet



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.11.21

South Main Span cont....:

- PP 70 - All stringers ok with packers in place, satisfactory - quiet
- PP 72 - Stringer no. 1 packer missing, stringer no. 2 packer showing signs of wear, stringer nos. 3-4 packers in place - **monitor**
- PP 74 - All stringers ok with packers in place, satisfactory - quiet
- PP 76 - All stringers ok with packers in place, satisfactory - quiet
- PP 78 - Stringer no. 1 ok packer in place, Stringer nos. 2-4 showing signs of wear - **monitor**
- PP 80 - All stringers ok with packers in place, satisfactory - quiet
- PP 82 - Stringer nos. 2 & 3 packers missing. Stringer nos. 1 & 4 ok – **Noisy**
Billet no. 4 bolt missing on west face
- PP 84 - Stringer no. 1 packer missing, stringer no. 2 packer showing signs of wear, stringer no. 3 missing and stringer no. 4 showing signs of wear – **Noisy**
Billet no. 4 has 4 no. bolts missing on west face
- PP 86 - All stringers ok with packers in place, satisfactory - quiet
- PP 88 - All stringers ok with packers in place, satisfactory - quiet
- PP 90 - Stringer no. 1 showing signs of wear, stringer nos. 2-4 satisfactory - quiet
- PP 92 - Stringer nos. 1 & 3 packers missing. Stringer no. 4 ok – **Noisy**
- PP 94 - All stringers ok with packers in place, satisfactory - quiet
- PP 96 - All stringers ok with packers in place, satisfactory - quiet
- PP 98 - Stringer nos 1 & 3 packers in place showing signs of wear, stringer nos. 2 & 4 packers missing - **Noisy**
- PP 100 – Stringer no. 1 showing signs of wear, stringer nos. 2-4 packers in place, satisfactory - quiet