

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. : Date.:

F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Viaduct Expansion (Combe) Joints\Independent Inspections\Viaduct Expansion Joint Weekly Inspection. January 2015\Combe Plate Weekly Survey Sheet 2015.03.30.Doc



Combe plate weekly survey sheet DATE. 2015.03.30



 $\label{eq:F:Eensineering} F:\ Ensineering\ E2 - Inspections\ E2.1 Bridge\ Joints\ Viaduct\ Expansion\ (Combe\) Joints\ Independent\ Inspections\ Viaduct\ Expansion\ Joint\ Weekly\ Inspection.\ January\ 2015\ Combe\ Plate\ Weekly\ Survey\ Sheet\ 2015.03.30.Doc$