

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. : ..... Date.: .....

F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Viaduct Expansion (Combe ) Joints\Independent Inspections\Viaduct Expansion Joint Weekly Inspection. January 2015\Combe Plate Weekly Survey Sheet 2015.04.20.Doc



Combe plate weekly survey sheet DATE. 2015.04.20



 $\label{eq:F:Eensineering} F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Viaduct Expansion (Combe ) Joints\Independent Inspections\Viaduct Expansion Joint Weekly Inspection. January 2015\Combe Plate Weekly Survey Sheet 2015.04.20.Doc$