




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.06.14..



Comments. :

On the Northbound Carriageway (West Side) NW2. Combe plate repaired on nightshift 2015.06.15/16. By Engineer K. Horn . Inspected for movement & sound by bridge inspector G.Elliott.

On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over ∴ Combe plate repaired on nightshift 2015.06.17/18. By Engineer K. Horn . Inspected for movement & sound by bridge inspector G.Elliott.

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out
On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over
Southbound Carriageway SE2 – there is slight movement on the west side.



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.06.14..