

Comments. :

On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over: Combe plate repaired on nightshift 2015.07.22. By Engineer G. Hall; inspected by bridge inspectors G.Elliott & T. Liebisch; slight movement & sound detected - will monitor.

On the Northbound Carriageway (West Side) SW1 - repair previously carried out 06.01.15 by Engineers - noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. :

Date.:

H:\Viaduct Expansion Joint Weekly Inspections 2015\Combe Plate Weekly Survey Sheet 2015.07.24.Doc





Combe plate weekly survey sheet DATE. 2015.07.24.