




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.08.14.



Comments. :

On the Southbound Carriageway SE2 – **Combe plate repaired on nightshift 2015.08.12/13**

By Engineer G. Hall; inspected by bridge inspectors G.Elliott & W. Forrest.2015.08.14 ; slight movement & sound detected - will monitor.

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out

On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over

Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. :

Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.08.14.