




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.08.21.



Comments. :

On the Southbound Carriageway SE2 – inspected by bridge inspector G. Elliott. 2015.08.14 ; slight movement & sound detected - will monitor.

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out
 On the Southbound Carriageway SE4 – slight movement/ slight noise evident when heavy vehicles pass over
 Southbound Carriageway SE2 – there is slight movement / slight noise evident.

Inspectors. : Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.08.21.